


September 10, 2020

Enclosed are my diagrams of the elevator that Frank installed in the corn crib. It had to be a commercial unit, and the installation must have been an accomplishment. I think that I saw another installation, common where the scoops went below and across the drive. I think the hopper gave is some trouble. It would not work with a tractor or gas engine.


Bruce showed an outside elevator. Jon thought that a gas engine was used. I think they used a tractor most of the time. At one time, there was a system where two horses would go around in a circle and run it. I think I remember seeing it, not using it. We had such an elevator in northwest Green county.

Dick Lindgren




Ground Floor of Corn Crib

R Lindgren 2020



R. Lardgren 2020

Longitudinal Section of
Corn Crib, South of Middle



Cross section of
middle of corn crib

B. Lindgren 2020